

# Current owner's itemized re-fit works list.

#### **2013MY GRADY WHITE 360 EXPRESS**

The following has been completed on "White Noise" since the purchase in August of 2020:

#### **Outside:**

- 1. New Ultra Anchor and 50 meters of 8mm short link anchor chain.
- 2. New Lumar windlass gypsy to accommodate 8mm short link chain.
- 3. New foot switches for the anchor windlass.
- 4. New Stainless Steel fender holders (4) on bow rail.
- 5. New dock lines and line keepers.
- 6. New Soft flooring expanded vinyl ester decking installed on all walking surfaces.
- 7. New windscreen washer spray nozzles.
- 8. Replaced 4 skin fittings for seawater intakes for live well, raw water, gen set, and refrigeration/AC.
- 9. Removed and resealed 8 windows across front windscreen.
- 10. New dark blue hull wrap from rub rail to waterline.
- 11. All snap anchors have been replaced and all screws in all exterior trim have been replaced in the cockpit and helm station annually.
- 12. New Precision Carbon Fiber outriggers with new rigging.
- 13. New helm station/Captain's chair pedestal (Grady White original equipment). New folding foot rest installed.
- 14. New handheld shower/spray nozzle in bait station sink in cockpit and transom shower.
- 15. New upholstery in cockpit (bolsters and seats, and all helm station seating.
- 16. New shotgun rigger.
- 17. Annually, full detail including all bright work.
- 18. Annually, full hull and engine leg anti-foul.

#### Inside main cabin:

- 19. New 32" smart television (12V) with Apple TV
- 20. New Galvanic Isolator.
- 21. New CO detectors (2) in main cabin.
- 22. Converted Galley fridge to operate on 12v.
- 23. New forward berth bolster upholstery.
- 24. New upholstery for settee, bumpers, and new custom fit berth covers for forward and mid cabin berths.
- 25. New tempurpedic mattress toppers made to fit to mid-cabin and forward berth with zip off covers for easy cleaning.
- 26. New forward berth hatch window frames with black-out and fly-screen closures.

# **Electrical and lighting**

- 27. Completed generator service, including heat exchanger descaling and fuel filter replacements, serviced annually since.
- 28. New Victron 3 Kw inverter charger installed.
- 29. Four 125-amp hour Lithium-ion batteries (500-amp hours) installed as house batteries.
- 30. New engine-start batteries installed, 75-amp hour versus previous 60-amp hour.
- 31. New 60-amp battery charger installed versus previous 40-amp for quicker battery recovery. New switching panel installed in battery box to enable using AMG or lithium batteries for engine start.
- 32. Two Victron 30-amp and two Victron 18-amp DC-DC chargers installed to maximize use of engine generated power for house battery charging (to limit need for long term generator running.)
- 33. New Victron battery management system.
- 34. Removed redundant electrical equipment and cleaned up wiring in several spots.
- 35. New wiper motors, arms, and blade assemblies (Re-wired electrical cabling for the wiper motors.)
- 36. Serviced motor for bow thruster, new bow thruster battery and battery charger installed. (Bow thruster tunnel flares were moulded and installed with the entire assembly fiberglassed into position.
- 37. 3 new high power underwater lights (white or blue) on stern. Each with an individual circuit breaker to disconnect if needed.
- 38. New down lights in the main cabin and head.
- 39. New 12V blue strip lighting in cockpit under gunwales and in main cabin forward berth courtesy lighting alcove.
- 40. All bilge pumps replaced.
- 41. New live well pump.
- 42. New raw water pump
- 43. New freshwater pump
- 44. New, larger shower sump with external gulper pump
- 45. 3 new down lights for helm station ceiling.
- 46. Installed a new breaker (15 amp) at switch panel for underwater lights.
- 47. Installed blue courtesy light in helm.
- 48. New Shore Power receptacles and (2) new shore power cables
- 49. New Siren Marine 3 alarm and system monitoring with new motion detector, cabin entry sensor, high water sensor, shore power sensor, battery sensor, engine sensor, with GEO-fence capability and GPS location monitoring.
- 50. Segregated the control systems for the refrigerated fish box from the cockpit cooler refrigeration for independent operation.
- 51. New cabin and helm station A/C units.
- 52. Installed separate bilge pump in the centre-bilge to manage rain/wash water.
- 53. Installed new dash panel for helm master.

- 54. 3 new 12V Scirocco fans installed (2 in helm station and 1 in main cabin.)
- 55. AIS system upgraded with new transceiver and aerial.
- 56. 2 New Furuno 16" chart plotters installed and integrated with the Helm Master system.
- 57. New Furuno 3D multi-beam transducer and sounder installed.
- 58. New Furuno closed array Radome.
- 59. New Furuno Sat Compass
- 60. New Cell-Fi Go system for improved cellular coverage offshore.
- 61. New Black Hawk cell booster system with aerial
- 62. Replaced all aerial bases with stainless steel.
- 63. Installed new Scan Strut aerial mast for new radar, Sat Compass, AIS, GPS and Cell-fi Go aerials and anchor light.
- 64. Installed 2<sup>nd</sup> VHF radio with new aerial. Installed new aerial for existing VHF radio.
- 65. Added a 2<sup>nd</sup> EPIRB.
- 66. 6 x New JBL speakers installed through main cabin, helm station and cockpit. To accompany the Fusion Bluetooth audio system.

### **Outboard Power Plant:**

- 67. New engines, TWIN Yamaha 350 hp outboards with engine covers. (Engines serviced every 100 hours by Brisbane Yamaha. Installed in October 2020 and currently have 730 hours each.
- 68. New Yamaha Helm Master system. (joystick, autopilot, digital electric steering.)

## Spare parts (Included with sale):

- 69. Two new bilge pumps pre-wired and plugged.
- 70. New refrigeration cooling pump, pre-wired. (a separate waterproof safety outlet installed at the pump location to avoid need for electrical work should pump need replaced. Simply mount the new pump, connect the plumbing and plug in.
- 71. New pressure accumulator for freshwater system.