

MARINE CRAFT INSURANCE RISK EVALUATION

Please provide an answer to each question with comments.
Where question does not apply to vessel write N/A.
If additional information necessary please attach separate sheet.

OWNER: Victorian Sailing School POLICY/QUOTATION NUMBER: V244078
 ADDRESS: 31 Eastern Beach Road, Geelong SLIPPING DATE: 13/07/17 /
 TELEPHONE NO: 0409508754 INSPECTED AT: Royal Geelong Y.C
 EMAIL ADDRESS: matthews.david.i@edumail.vic.gov.au VESSEL NAME: Kyrano
 HIN/REGISTRATION/SAIL NO.: 1122 AFLOAT SLIPPED
 BUILDER: Unknown DESIGN: Thunderbird RIG: Fractional
 DATE LAUNCHED: 1990 Beam: 2.4m LOA: 8m Draft: 1.5m
 CONSTRUCTION MATERIAL - HULL: GRP DECK: GRP KEEL: Cast Iron

NOTE: BOATS OVER 30FT MUST BE SURVEYED BY A QUALIFIED MARINE SURVEYOR

HULL CONSTRUCTION/CONDITION

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Keel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Hairline fracture visible in fairing around hull/keel join
Keelbolts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	14 bolts & nuts, surface corrosion on a few nuts
Surface U/W	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2 PAC paint finish
Surface A/W	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Minor cosmetic damage, scratches. Paint is degrading
Deck	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Timber capping at transom is split
Cockpit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cosmetic gelcoat crazing in port lower corner
Coach-house	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1 window is crazed
Frames	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stringers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Bulkheads	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Plywood b/heads laminated to hull
Cabin/Interior	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Basic, functional layout
Marine Toilet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Porta potti
Seacocks	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Skin Fittings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Transducers
Cockpit Drains	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Propeller	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Propeller Shaft	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Outboard motor
Propeller Skeg	<input type="checkbox"/>	<input type="checkbox"/>	N/A

HULL CONSTRUCTION/CONDITION (cont'd)

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Stern gland	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Rudder	<input checked="" type="checkbox"/>	<input type="checkbox"/>	GRP blade
Rudder Mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tube
Rudder Stock/Gland	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tube to deck, s/steel rudder stock
Steering Linkages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Timber tiller degraded
Auxiliary Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Outboard motor
Chain Plates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Below deck spans covered with carpet, s/steel strap plates
Stemhead Fitting	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Lower fastening bolt rusty

Recommendations: Monitor fairing crack around keel socket. Clean keel bolt nuts. Re-glue split timber on transom. Repair or replace tiller. Remove & assess lower stemhead fastening.

MOTOR INSTALLATION/CONDITION

PETROL: DIESEL: INBOARD: OUTBOARD: STERN DRIVE: JET:

BRAND: Yamaha MODEL No.: 8CMH SERIAL No.: 1017766 H.P.: 8 AGE: _____

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Installation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Mounted in outboard well
Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Exhaust	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Fuel Lines/Fittings	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Hose degraded at engine end
Fuel Tanks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Portable tank secured in place
Filler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Venting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Through tank cap
Connection & Lines	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Electrical Harness	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Electrical Fitting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Basic 12-volt system
Stove	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Gas Bottles	<input type="checkbox"/>	<input type="checkbox"/>	Inc. Gas Compliance Plate No.: <u>N/A</u>
Connections & Lines	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Position	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Venting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N/A
Gas Detector	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Batteries	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Small 12-volt battery, flat
Mounting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Sits in small battery box
Bilge Pump - Manual	<input type="checkbox"/>	<input type="checkbox"/>	No bilge pump fitted, bailing bucket onboard
- Electrical	<input type="checkbox"/>	<input type="checkbox"/>	N/A

Recommendations: Cut off degraded section of fuel hose. Charge or replace battery & test electrical systems. Fit manual or electric bilge pump.

MAST, SPARS, RIGGING AND SAILS

MAST MATERIAL: ALUMINIUM TIMBER CARBON OTHER: Painted

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Mast/s	<input checked="" type="checkbox"/>	<input type="checkbox"/>	TYPE: MASTHEAD: <input type="checkbox"/> FRACTIONAL: <input checked="" type="checkbox"/> HOW OLD: <u>Unknown</u> WHEN LAST SERVICED: <u>Unknown</u>

Mast Step	<input checked="" type="checkbox"/>		Stepped on internal step
Boom/s	<input checked="" type="checkbox"/>		Gooseneck pin hole is elongated
Spin. Pole/Jockey Pole			
Rigging	<input checked="" type="checkbox"/>		ROD <input type="checkbox"/> WIRE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> AGE <input type="checkbox"/> Unkn
Spreaders	<input checked="" type="checkbox"/>		No. of <input type="checkbox"/> 1 <input type="checkbox"/> INLINE <input type="checkbox"/> SWEPT BACK <input type="checkbox"/> Yes <input checked="" type="checkbox"/>
Base Attachments	<input checked="" type="checkbox"/>		Secure
Chain Plates	<input checked="" type="checkbox"/>		Strap plates though bolted to internal frames
Hydraulics			N/A

Sail Inventory: No sails were onboard

Sail Age: _____

Sail Conditions: _____

Date Mast &/or Rigging last serviced & by whom: Unknown when last serviced, no visible broken strands

SAFETY EQUIPMENT

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Anchor & Warp	<input checked="" type="checkbox"/>		Danforth anchor, rope & chain warp
Flares		<input checked="" type="checkbox"/>	Expired Mar 2016
Fire Extinguisher		<input checked="" type="checkbox"/>	Due for service
Spot Light	<input checked="" type="checkbox"/>		Torch
Lifejackets			No life jackets on board
Navigation Lights		<input checked="" type="checkbox"/>	Mounted below sheerline, could not test as battery is flat
Life Raft			N/A
Pulpits		<input checked="" type="checkbox"/>	Port base is broken off
Pushpits			N/A
Staunchions/Lifelines			N/A

Recommendations: Replace flares. Service fire extinguisher. Put life jackets on board. Mount navigation side lights above sheerline. Repair pulpit base.

GENERAL REMARKS AND RECOMMENDATIONS

RESTRICTED WATERS

OPEN WATERS

Kyrano is a standard GRP built Thunderbird yacht. The hull, deck and framing all look structurally sound. The cosmetic appearance is fair. There are several small maintenance items listed in the report. The mast should be serviced and the rigging replaced in the near future due to the unknown exact age. The pulpit should be repaired or removed. The vessel is used for teaching sailing on Corio Bay.

The safety equipment should be updated prior to using the vessel.

PRIVACY ACT 1988

The *Privacy Act 1988* requires us to tell you various things. We collect your personal information to decide whether to provide you with a quote or a policy, to set the terms and conditions of your policy, to compile data and to handle claims.

We will also require your personal information to mail you the Club Marine magazine.

Club Marine Limited may need to disclose your personal information to third parties such as Allianz Australia Insurance Limited, other insurers, loss adjusters and agents, or other parties as required by law.

You have the right to access your personal information and change it at any time.

Please contact your nearest Club Marine Office and advise us of the changes. If you do not agree to the collection of your personal information then unfortunately we will be unable to process your Insurance Risk Evaluation.

DISCLAIMER:

Club Marine acknowledge that whilst all reasonable attempts have been made to detect any defects present there may exist hidden or latent defects or those that cannot be discovered without interfering with the structure of the vessel. In consideration of the person or company to whom this form has been issued, carrying out a visual evaluation of the vessel on behalf of the owner of the vessel concerned, Club Marine undertakes not to instigate any legal proceedings or action against the person or company. Club Marine acknowledge that the evaluation document is to be used solely by Club Marine to evaluate the insurance risk of the boat concerned and for no other purpose.

Authorised Marine Surveyor Authorised Shipwright

Name: Brendan Garner Signature:  Date: 18/07/2017/

Trading Name: Power Drive Marine

Email Address: service@powerdrivemarine.com.au Contact Number: 0408820662

Please attach broadside photograph of boat



Ph. 1300 00 2582
Fax. 1300 44 2582
Email. sales@clubmarine.com.au
Mail. 40 The Esplanade Brighton VIC 3186

OFFICES - Club Marine Limited ABN 12 007 588 347

- Victoria - 40 The Esplanade, Brighton 3186
- New South Wales - 2 Market Street, Sydney 2000
- Queensland - 1029 Manly Road, Tingalpa 4173
- South Australia - Level 6, 89 Pirie Street, Adelaide 5000
- Western Australia - 24 Mews Road, Fremantle 6160