

	Main Halvard	100'	Replaced Jan 2014			
	Genoa Sheets (2)	60'	Replaced Apr 2023 (12mm double braid poly - 16m each) www.rocecalore.com.au			
	Main Sheet	60'	Replaced Apr 2023 (12mm double braid poly - 16m)			
	Flirtail Halvard	35m				
	7/16"					
	Staveall Topping	45'				
	Main Topping	100'				
	Staveall Sheet	30'				
	Main Reefing (1)	30'	Replaced Apr 2023 (12mm double braid poly)			
	Main Reefing (2)	42'	Replaced Apr 2023 (12mm double braid poly)			
	Main Reefing (3)	22'	Replaced Apr 2023 (12mm double braid poly)			
	Main Outhaul	22'	Replaced Apr 2023 (12mm double braid poly)			
	Vang	35'				
	3/8"					
	Yankasa Furling Line	85'	Replaced Oct 2023			
	Staveall outhaul and reefing	36'	Replaced reefing line with new Reefit furler 24/8/23 Bravo Sails			
	1/4" line					
	Reefing ties					
	Flan Halvards (2)	44'				
Standing Rigging						
	New 2008					
	Racketsw Forestay	3/8"				
	Ton Rhearsw	3/8"				
	Lower Shrouds	5/16"				
	Inner Stay	5/16"	Replaced with new Reefit furler 24/8/23 Bravo Sails			
	Fixed backstays (not Whisker Pole)	1/4"				
	Forespar 403103 LC-13-24					
Rig Dimensions						
	Source Fraser Smith @					
	I	45.5'				
	P	38.33'				
	F	15.68'				
	J	10'				
House Bank			New 2022 (4 x 6v AGM batteries in 2 banks of 250Ah each = 500Ah total) FullRiver? Should last 8 - 12 yrs		Installed Tune AJH	New Feb 2015 14/2/2015 Tuesen T145 W44 520
Main inverter (110V)	Victron Multi Plus inverter/charger Model	12/110/3000	New June 2017 replaced original Vecrtron Phoenix multiplex			
Secondary inverter (240V)	PS-1000	12 volts DC, 110 volts AC.	Installed in aft hanging locker with 100A breaker on starboard bulkhead behind drawer under quarter berth. Connected to power board above			
	New 2014	12 volts DC 240 volts AC	1000W continuous, 2000W surge			
Starter battery			Charged from Alternator and 'flow through' (one way) from solar / wind Replaced Nov 2022 (update details)			
Battery Box				Installed Tune CCA	New Feb 2015 14/2/2015 AGM (Minimum 31 800 +	
Water Maker						
	Length	23"				
	Width	14"				
	New 30/1/08		Need to flush this with fresh water every 5 to 10 days or pickle every 6 months if not being used regularly			
	Type	Spectra Cape Horn				
	Charcoal Filter	Extruded Charcoal	Replaced Mar 24 www.southernseasmarine.com for soares			
	Volume	Metrixx 10-25L-190-075 3 Micron nominal filtration No release of carbon finings 14 Gall/Hr (30l/h) Clark Pump reconditioned Oct 2015	Replaced Mar 24 New end cap (right side - was cracked), SS tube and pressure connectors - March 24			
Fresh Water						
	Pump Model	PAR Max 4 3.8 GPM 30000002				
	Main fresh water filter	Metrixx (X1501C)	1 linder sink			
	Seawall water outfilter	Metrixx (X1501C)	0.1 micron filter			
Instruments						
	Raymarine Self Sealing Through hull	Raymarine ST60	Raymarine new 8/10/07			
	Speed	A22001				
	Depth	A22002				
	Wind	A22012				
	Pitcher	C90				
Below Deck Autoclot						
	Model	ST6001+				
	Controller	F12068				
	Type 2 Linear Short Drive Core Pack	m81131 SSC (400G) E12092				
Tiller Pilot						
	Model	Attaches to wind vane mount (replaces the vane) ST1000				
SSB						
	Model	New 2007				
	Serial	ICOM IC-M802				
	Tuner	103864 AT-140 Auto	UPC 731797302731			
VHF						
	Model	New Jan 2008	update new details + new AIS transceiver - Oct 2023			
	Serial	ICOM IC-M422 1112077				
	Command mike in cockpit		Spares behind cushions at the corner of the stbd side settee			
Head						
	Model	New Dec 2013				
	Installed	TMC Electric 10/1/2014	New macerator (imperial seal etc) March 2024			
Windlass						
	Model	New 2002				
	Capacity	Lofrans Tigres 1200W 3/8" 40mm	Spares 9mm mouse in locker			
	Remote control		New controller Oct 2023 (had still working - lost ac spares)			
Air Conditioner						
	Manufacturer	OnixAir				
	Model	FX16				
	Capacity	16,000 BTU				
	Serial #	M980002				
	Input min	14A @115V	1 600 Watts			
	Input Max	75A @115V	8 600 Watts			
Lights						
	Front RL-Cable	New Aug 2023	Hella marine lights fitted by Menuv at North Haven Marina (0433 999 001)			
Portholes						
	Rectangular	512SS x 8 5RSS x 4	https://newfoundmetals.com/product/rectangular-ss-cortlight/ https://newfoundmetals.com/product/round-ss-cortlight/ New SS screens Feb 2021			
Wind Generator						
	Type	New 2021	Outback marine www.outbackmarine.com.au (07) 5563 9088	Old KISS generator		
	Model	Primus wind power (12V) AIR silent X		Diode pack TRANSPO-CN	DR5040-1960	
Solar panels						
	Rear	180W	New 2021 SP-EN180W	Used to have 295W total		
Solar Power Regulator						
	REDARC		New 2021 (along with whole new panel, remote monitor, fuses, battery charger etc)			
Gas cylinders						
	2x 2.5kg	Empty 2kg	Jan 2023 replaced with 2 4.5kg gas swap cylinders			
	1x 4.5 kg	Empty 4.4kg	Number 1 = 4.17kg, 2 = 4.35kg 8.4kg			
Dinghy						
	SKP UL270	On Davits	Replaced 2022 with Skis dingy (update details)			
	Outboard	ePropulsion Spirit 1.0 Plus	SN D5PS2N70001 (New 28/10/23 - registered for 5 yr warranty)	9.8 HP Tohatsu	SN 0258424B	
Literati	Viking (UKL - ISO 9650-1)		New Viking 4 man L/R May 2022 (Viking Sydney)			
Genset	Honda EU22i	Serial No EAMT-2262049 2.2kw	New 17 Sep 2020 (Not currently on boat)			
Air compressor	Nardi diving hookah 12v battery	Esprit 12v 180lpm - 3ltr tank 100ah sealed deep cycle	New 17 Sep 2020 New 17 Sep 2020			
Victron MultiPlus settings	Default apart from absorption voltage...					
DIP	Step 1 (push UP after	Step 2 (Push DOWN after	Step 1 explanation	Step 2 explanation		
	8 on	on	50A max AC input (default)	Absorption Voltage 14.7V		
	7 on	off	50A max AC input (default)	Absorption Voltage 14.7V		
	6 on	off	Max time in absorption	Absorption Time 4hrs (default)		
	5 off	on	Auto Economy Sw (default)	Adaptive Charge (default)		
	4 on	off	Charge Current 75% (default)	Dynamic Current Limiter (default)		
	3 off	off	UPS off	UPS function (default)		
	2 off	off	N/A	Converter Voltage 120V (default)		

1 off off N/A

Converter Freq 60Hz (default)

Previous owners

1986 Original boat name:
Makaratha.

United Airlines pilot bought new and owned her in Florida for 13 years. Jack said that he kept her in a lake for her early life, but doesn't remember any details. He apparently didn't do much more than motor over to the Bahamas periodically. Original sails were still in good shape when I bought. He hadn't moved her for 3 years or so and the engine required a top overhaul with only 800 hours

Purchased by Jack
Warren in 1999

Renamed to Anthem

Jack spent a lot of time sailing in the Bahamas before a major refit. He stocked the boat with spares before heading from Florida through the Panama canal over to Fiji and then down to New Zealand where some further work was done including sails and rigging. He then imported the boat into Australia in Brisbane and sold it to buy a larger vessel (Hylas 46).

Purchased by Dave
Edwards and Terry
Jackson Feb 2013
Purchased by Markus
and Pauline Nolle
July 2020 - 2024

Renamed to Venture
Not renamed

Sailed the South East (SA, Vic and Tas) and East coast (NSW, Qld) of Australia. Fitted new 50hp Kubota engine. New mainsail and some rigging (?). Finally sailed from SA to Portland in Vic in late July 2020 during the Covid-19 pandemic crisis to handover the boat to the new owners (Markus and Pauline) just in time to get home to SA before the borders closed!
Sailed extensively in Bass Strait / islands - Victorian and Norther Tas waters (based out of Apollo Bay). Then sailed to SA and sailed the gulfs, Kangaroo Island around to Port Lincoln and around the West Coast out to Pearson Island. Then bought a Hylas 46 (very funny as this was exactly what Jack did! Go figure... :-)