



MARINE CRAFT INSURANCE RISK EVALUATION

Please provide an answer to each question with comments.
Where question does not apply to vessel write N/A.
If additional information necessary please attach separate sheet.

OWNER: Erik Pringle POLICY/QUOTATION NUMBER: N271807
ADDRESS: 21/54 Wrights rd Drummoyne SLIPPING DATE: 1 / 8 / 2018
TELEPHONE NO: 0414 600 313 INSPECTED AT: Woolwich dock
EMAIL ADDRESS: erik.wadner@hotmail.com VESSEL NAME: 'Eastern star'
HIN/REGISTRATION/SAIL NO.: AUWVA 102687GP3 AFLOAT ☐ SLIPPED ☒
BUILDER: Binks Yachts DESIGN: Farr B30 RIG: Alloy
DATE LAUNCHED: 1989 LOA: 9.4M
CONSTRUCTION MATERIAL - HULL: GRP DECK: GRP KEEL: GRP steel frame
lead bulb

NOTE: BOATS OVER 30FT MUST BE SURVEYED BY A QUALIFIED MARINE SURVEYOR

HULL CONSTRUCTION/CONDITION

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Keel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Keelbolts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Surface U/W	<input checked="" type="checkbox"/>	<input type="checkbox"/>	medium antifoul build up
Surface A/W	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Deck	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Cockpit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Coach-house	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Frames	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stringers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Bulkheads	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Some deterioration in non structural areas
Cabin/Interior	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Marine Toilet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Seacocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Skin Fittings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Cockpit Drains	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Propeller	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Propeller Shaft	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Sail drive
Propeller Skeg	<input type="checkbox"/>	<input type="checkbox"/>	N/A

HULL CONSTRUCTION/CONDITION (cont'd)

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Sternland	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N/a (Saildrive)
Rudder	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rudder Mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rudder Stock/Gland	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Steering Linkages	<input type="checkbox"/>	<input type="checkbox"/>	
Auxiliary Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N/a tiller steer
Chain Plates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stemhead Fitting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Recommendations: none

MOTOR INSTALLATION/CONDITION

PETROL: ☐ DIESEL: ☒ INBOARD: ☒ OUTBOARD: ☐ STERN DRIVE: ☐ JET: ☐
 BRAND: Volvo MODEL No.: 2002 SERIAL No.: 2300038156 H.P.: 18 AGE: Unknown

	ACCEPT	NON ACCEPT	COMMENTS/DETAILS/DESCRIPTION
Installation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Lines/Fittings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Tanks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Filler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Venting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Connection & Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical Harness	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical Fitting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stove	<input type="checkbox"/>	<input type="checkbox"/>	
Gas Bottles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N/a
Connections & Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Inc. Gas Compliance Plate No.: <u>GN434697</u> (No gas bottle)
Position	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Venting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Gas Detector	<input type="checkbox"/>	<input type="checkbox"/>	
Batteries	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Mounting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Bilge Pump - Manual	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
- Electrical	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Recommendations: none

MAST, SPARS, RIGGING AND SAILS

MAST MATERIAL:

ALUMINIUM ☒

TIMBER ☐

CARBON ☐

OTHER: _____

ACCEPT ☒ NON
ACCEPT ☐

COMMENTS/DETAILS/DESCRIPTION

Mast/s

TYPE: MASTHEAD: ☐ FRACTIONAL: ☒

HOW OLD: 1989 WHEN LAST SERVICED: 2018

Mast Step

☒

Boom/s

☒

Spin. Pole/Jockey Pole

☒

Rigging

☒

Spreaders

☒

Base Attachments

☒

Chain Plates

☒

Hydraulics

☐

ROD

WIRE

☒

AGE

New

No. of

1

INLINE

SWEPT BACK

☒

N/a

Sail Inventory: Mainsail, Furling headsail, spare headsail

Sail Age: Unknown

Sail Conditions: good

Date Mast &/or Rigging last serviced & by whom: 2018, Diverse Rigging

SAFETY EQUIPMENT

ACCEPT ☒ NON
ACCEPT ☐

COMMENTS/DETAILS/DESCRIPTION

Anchor & Warp

☒

Flares

☒

Fire Extinguisher

☒

Spot Light

☒

Lifejackets

☒

Navigation Lights

☒

Life Raft

☒

Pulpits

☒

Pushpits

☒

Stanchions/Lifelines

☒

Recommendations: none

GENERAL REMARKS AND RECOMMENDATIONS

RESTRICTED WATERS ☐

OPEN WATERS ☒

This vessel was found to be in good condition other than a bulge and cracking on the port aft area where the hull joins the keel. Subsequently the whole hull/keel join has been ground back and re-laminated by Chris Koreman Composites in late August 2018. I have included photos of some of this process in my email.

While the boat was in Woolwich dock shed the wine rigging was replaced and the mast inspected by Diverse rigging. I have inspected the repairs and consider them to be of a high standard.

PRIVACY ACT 1988

The Privacy Act 1988 requires us to tell you various things. We collect your personal information to decide whether to provide you with a quote or a policy, to set the terms and conditions of your policy, to compile data and to handle claims.

We will also require your personal information to mail you the Club Marine magazine.

Club Marine Limited may need to disclose your personal information to third parties such as Allianz Australia Insurance Limited, other insurers, loss adjusters and agents, or other parties as required by law.

You have the right to access your personal information and change it at any time.

Please contact your nearest Club Marine Office and advise us of the changes. If you do not agree to the collection of your personal information then unfortunately we will be unable to process your Insurance Risk Evaluation.

DISCLAIMER:

Club Marine acknowledge that whilst all reasonable attempts have been made to detect any defects present there may exist hidden or latent defects or those that cannot be discovered without interfering with the structure of the vessel. In consideration of the person or company to whom this form has been issued, carrying out a visual evaluation of the vessel on behalf of the owner of the vessel concerned, Club Marine undertakes not to instigate any legal proceedings or action against the person or company. Club Marine acknowledge that the evaluation document is to be used solely by Club Marine to evaluate the insurance risk of the boat concerned and for no other purpose.

☐ Authorised Marine Surveyor

☒ Authorised Shipwright

Name: Bill Olsen Signature: [Signature] Date: 7/9/18

Trading Name: Olsen Marine

Email Address: bill@olsenmarine.com.au Contact Number: 0903 320 651

Please attach broadside photograph of boat



Ph. 1300 00 2582
Fax. 1300 44 2582
Email. sales@clubmarine.com.au
Mail. 40 The Esplanade Brighton VIC 3186

OFFICES - Club Marine Limited ABN 12 007 588 347

- ☐ Victoria - 40 The Esplanade, Brighton 3186
- ☐ New South Wales - 2 Market Street, Sydney 2000
- ☐ Queensland - 1029 Manly Road, Tingalpa 4173
- ☐ South Australia - Level 6, 89 Pirie Street, Adelaide 5000
- ☐ Western Australia - 24 Mews Road, Fremantle 6160