



MARINE CRAFT INSURANCE RISK EVALUATION

OWNER: Chris Wilson	POLICY/QUOTATION NUMBER: QA32178115 Youi	
ADDRESS: 373 Ables Bay Road, Cygnet, Tasmania	SLIPPING DATE: 3 March 2022	
TELEPHONE NO: 0488978338	INSPECTED AT: Ables Bay	
EMAIL ADDRESS: cccoco@active8.net.au	VESSEL NAME: Fleetwing	
HIN/REGISTRATION/SAIL NO.: MAST Registration 38746, Sail No 6	<input type="radio"/> AFLOAT <input checked="" type="radio"/> SLIPPED	
BUILDER: Ostac Marine Brisbane	DESIGN: Farrier F9 Trimaran (folding)	RIG: Sloop
DATE LAUNCHED: 1990	LOA: 9.3m	
CONSTRUCTION MATERIAL - HULL: Glass over laminated western red cedar (cold molded)	DECK: Glass over western red cedar	KEEL: Centerboard

HULL CONSTRUCTION/CONDITON

	CONDITION	COMMENTS/DETAILS/DESCRIPTION
Keel	Good	Lifting centerboard in case glass over western red cedar
Keelbolts	N/A	Centerboard in case. Inspected and clear of any cracking or deformity
Surface U/W	Good	Copper coat antifouling over epoxy
Surface A/W	Good	Epoxy based paint in good condition
Deck	Good	Glass over plywood. Thoroughly checked throughout for cracking or deformity with particular attention to the hull arms. All found in very good condition. New trampolines on pontoons.
Cockpit	Good	Glass over western red cedar. Epoxy paint. Free of cracking or stress.



SALUS MARITIME
ABN [82 008 428 437](https://abn.gov.au/abn/82008428437)
23 Pipeclay Esplanade
Cremorne Tasmania 7024

WWW.SALUSMARITIME.COM
contact@salusmaritime.com
Tel +61 (0) 459467558
Marine Survey and Consultancy

	CONDITION	COMMENTS/DETAILS/DESCRIPTION
Coach-House	Good	Glass over western red cedar. Epoxy paint. Free of cracking or stress.
Frames	Good	Glass over ply. Free of cracking or stress.
Stringers	Good	Glass over western red cedar. Free of cracking or stress.
Pontoons	Good	Glass over western red cedar. Epoxy paint on outside. Checked inside and out Free of cracking or stress. Slight leak from buoyancy caps when under pressure while sailing and ponon under water. Bilge pumps installed in pontoons to remove water.
Arms	Good	Aluminum folding arms in good condition. Free of cracking or corossion
Bulkheads	Good	Fiberglass over Plywood bulkheads
Cabin/Interior	Good	Glass over western red cedar. Epoxy paint. Free of cracking or stress.
Marine Toilet	Good	Portable style. No sea cocks
Seacocks	Good	Bilge pump drain only at waterline in good condition. Galley drain above waterline in good condition.
Skin Fittings	Good	
Cockpit Drains	Good	Self draining cockpit
Propeller	Good	
Propeller Shaft	Good	
Propeller Skeg	Good	
Stern gland	N/A	
Rudder	Good	Lifting Rudder built into cassette Glass over western red cedar. Epoxy paint. Free of cracking or stress.
Rudder Mounts	Good	
Rudder Stock/Gland	N/A	
Steering Linkages	Good	
Auxiliary Steering	N/A	
Chain Plates	Good	Stainless steel chain plates in good condition
Stemhead Fitting	Good	Stainless steel chain plates

Hull Construction/Condition Recommendations:

Hull, arms and pontoon inspected in good condition. Particular attention was paid to areas around folding arms and high stress areas of trimaran. No signs of stressing. Vessel in very good condition.

MOTOR INSTALLATION/CONDITION

<input checked="" type="checkbox"/> PETROL <input type="checkbox"/> DIESEL		<input type="checkbox"/> INBOARD <input checked="" type="checkbox"/> OUTBOARD		<input type="checkbox"/> STERN DRIVE <input type="checkbox"/> JET <input checked="" type="checkbox"/> LEG <input type="checkbox"/> SHART	
BRAND: Yamaha	MODEL No: FT9.9LE 4 Stroke	SERIAL No: 1028515	H.P: 9.9HP	AGE: New 2016	

	CONDITION	COMMENTS/DETAILS/DESCRIPTION
Installation	Good	
Controls	Good	
Exhaust	Good	
Fuel Lines/Fittings	Good	
Fuel Tanks	Good	25L tank in port cocopit locker
Filter	Good	
Venting (Motor)	Good	Natural ventilation
Connection & Lines (Motor)	Good	
Electrical Harness	Good	
Electrical Fitting	Good	
Stove	Good	Origo 3000 Metholated spirit stove
Gas Bottles	N/A	Inc. Gas Compliance Plate No.: No gas onboard
Connection & Lines (Gas)	N/A	
Position	N/A	
Venting (Gas)	N/A	
Gas Detector	Good	Carbon monoxide gas detector
Batteries	Good	110AH 12V AGM midships. Secured in good condition. 12V lead acid starting batter in battery box near cockpit hatch
Mounting	Good	
Bilge Pump - Manual	Good	Hand pump
Bilge Pump - Electric	Good	Bilge pumps in each pontoon, roaving electric pump in main hull

Motor Installation/Condition Recommendations:

MAST, SPARS, RIGGING AND SAILS

MAST MATERIAL:	<input checked="" type="radio"/> ALUMINIUM <input type="radio"/> TIMBER <input type="radio"/> CARBON <input type="radio"/> NA <input type="radio"/> OTHER OTHER:
----------------	--

	CONDITION	COMMENTS/DETAILS/DESCRIPTION		
Mast/s	Good	TYPE: <input type="radio"/> MASTHEAD <input checked="" type="radio"/> FRACTIONAL <input type="radio"/> NA HOW OLD: _____ LAST SERVICED: 2022 Serviced and re rigged by oyster cove rigging 2022.		
Mast Step	Good			
Boom/s	Good			
Spin. Pole/Jockey Pole	Good			
Rigging	Good	ROD:	WIRE:	AGE:
		Spectra rigging		
Spreaders	Good	No. of: 2	INLINE:	SWEPT BACK: 2
Base Attachments	Good			
Chain Plates	Good			
Hydraulics	N/A			

Sail Inventory: Dynema mainsail, storm sails, genoa, asymmetrical spinnaker
Sail Age: 2018
Sail Conditions: Good
Date Mast &/or Rigging last serviced & by whom: 2022 by oyster cove rigging

SAFETY EQUIPMENT

	CONDITION	COMMENTS/DETAILS/DESCRIPTION
Anchor & Warp	Good	
Flares	Good	Inshore flare kit. Expiry 06/24
Fire Extinguisher	Good	
Spot Light	Good	
Lifejackets	Good	
Navigation Lights	Good	
Life Raft	Good	
Pulpits	Good	
Pushpits	Good	
Stanchions/Lifelines	N/A	

Safety Equipment Recommendations:
Epirb GMENT600 SRL 1612466926

GENERAL REMARKS AND RECOMMENDATIONS

RESTRICTED WATERS OPEN WATERS

Farrier fleetwing F9 Trimaran underwent a substantial refit in 2018 where all equipment was overhauled or replaced. Workmanship of the original build and the refit have been completed to a high standard. The trimaran has folding arm system typical of the farrier design. The folding arms and pontoons were inspected in great detail for signs of stress and found to be in very good condition.

It is obvious in this inspection that the owner keeps the vessel maintained to a very high standard and uses the vessel often.

Authorised Marine Surveyor Authorised Shipwright

Name: Richard Hewson
Trading Name: Salus Maritime
Email Address: salusmaritime@gmail.com

Signature: 

Date: 5/3/2022

Contact No: 0402108301

